

# Final Reclamation Inspection

May 6, 2019

Operator: HARSH INTERNATIONAL INC - 38470

API #: 05-123-12565

Inspection Document #: 697500078

Weld County, CO

NWNE Section 6 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565



**Photo 1.** Photo taken from a portion of the access road, facing West. Access road is evident, with gravel, and has not been reclaimed per Rule 1004. It does not appear that the Operator has performed final reclamation activities throughout the access road and tank battery. Vegetation mainly consists of Cheatgrass and Kochia, all undesirable species. Reference area vegetation appears to be cropland, Winter wheat.

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565




**Photo 2.** Photo taken from a portion of the access road. Photo illustrates Cheatgrass.

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565



**Photo 3.** Photo taken from the eastern tank battery, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565



**Photo 4.** Photo taken from the southeastern tank battery, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565



**Photo 5.** Photo taken from the central tank battery, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: HARSH #2  
API #: 05-123-12565



**Photo 6.** Photo taken from the western tank battery, facing West. See comments under Photo 1.