

Inspection Photos
Location Name: Dillard USX AB 9-16
Location ID: 310218



Photo 1: Wellhead



Photo 2: Tank Battery

