

COMPLIANCE FOLLOW UP FORM

INFORMATION

Name	colen@horizonenvservices.com
Date	Mon Apr 29 2019
Well Name	LORENZ, ALICE GAS UNIT 1
API Number	50670695100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

Completed work description



Sprayed musk thistle in the reclamation area.
Site is complete.