

Inspection Photos
Location Name: NEITOS 23-28
API #: 05-071-06514
INSP. #:695100634



PHOTO 1: LOCATION




PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS
INACCURATE **Install sign to comply with Rule 210.b. CA DUE DATE
7/10/19**