

**Inspection Photos**  
**Location: Craig #1-7**  
**Inspection Date: 5/8/19**  
**All Photos taken by COGCC staff Kris Neidel**



**Photo 1 – looking south-east. Foreground shows access road. The area just past the access road is where the tank battery was. Some trash was observed on the location; gloves, bottles, cans.**



**Inspection Photos**  
**Location: Craig #1-7**  
**Inspection Date: 5/8/19**  
**All Photos taken by COGCC staff Kris Neidel**



**Photo 2 – looking north-northeast. This is where the well and pumpjack were. In the foreground is the access road that goes to the Yampa River. A piece of cable was observed in the grassy area north of well, per rule 603.f remove all trash. A deadman anchor was observed to the east of the well.**

