

Inspection Photos
Location: oxbow 0880 S29, loc 458790
Inspection Date: 5/9/19
All Photos taken by COGCC staff Kris Neidel



Photo 1 –looking west. Foreground shows area where trucks are parking for loading. The path over the flare line is where backhoe is driving to load trucks.



Inspection Photos

Location: oxbow 0880 S29, loc 458790

Inspection Date: 5/9/19

All Photos taken by COGCC staff Kris Neidel

Photo 2 – looking west. Foreground shows area where trucks are parking for loading. The path over the flare line is where backhoe is driving to load trucks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources