

## Inspection Photos

Location Name: PEPPLER-66N63W /17SWNW

Location #: 310651



**Photo #1**

**Peppler 17-12 (05-123-26749) Wellsite**

**Shut-In | SI**

**Emergency Number NOT posted**



**Photo #2**

**Peppler 17-12, 17-22 Battery**

**Shut-down**

**Illegible capacity – Condensate tanks**

**Inspection Photos**  
**Location Name:** PEPPLER-66N63W /17SWNW  
**Location #:** 310651



**Photo #3**  
**Peppler 17-12, 17-22 Battery**  
**East condensate tank - loadout**  
***Stained soil***



**Photo #4**  
**Peppler 17-12, 17-22 Battery**  
**West condensate tank - loadout**  
***Stained soil***