

# Inspection Photos

5/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313705

Inspection Doc. Number: 696200044

Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 1:** Photo taken from the southeast end of the location, facing northwest. Previous inspection documented a pump base remaining on the location, and that location remained predominantly undesirable weedy plant species. Inspection required operator to conduct reclamation in accordance with 1004.a. Photo shows concrete base has been removed. However, unable to find evidence that reclamation work beyond the removal of the base has been conducted.

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 2:** Photo shows concrete base has been removed. Photo also show no other reclamation activities appear to have been conducted on the location; unable to find evidence that revegetation/seeding activities have been conducted, or stabilization BMPs installed. Location remains predominantly exposed soil or undesirable weedy plant species. Photo also shows metal sign holder has been left at well site. This needs to be removed.



Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 3:** Photo taken from the location. Photo shows Canada Thistle (*Cirsium arvense*) establishing on the location. This is a Colorado State listed noxious weed and needs to be managed

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 4:** Photo taken from the northwest corner of the location, facing southeast. Photo shows reclamation on the entire location does not appear to have been conducted in accordance with 1004.a. Location remains exposed soil or predominantly undesirable weedy plant species.



Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 5:** Photo taken from the of the location. Photo shows Scotch Thistle (*Onopordum acanthium*) establishing on the location. This is a Colorado State listed noxious weed and needs to be managed.



Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 6:** Photo taken from the east end of the location, facing west. Photo shows location remains predominantly undesirable weedy plant species such as Cheat grass, Kochia, Scotch and Canada thistle. Unable to find evidence that reclamation has been conducted on the location in accordance with 1004.a

Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 7:** Previous inspection documented three (3) above ground steel tanks north of the location and required operator to remove in accordance with 1004.a. Photo shows tanks remain.



Inspection Photos  
Operator Name: PCR OPERATING LLC - 10657  
Location ID: 313705



**Photo 8:** Previous inspection documented three (3) above ground steel tanks north of the location and required operator to remove in accordance with 1004.a. Photo shows tanks remain.