

Inspection Photos
Operator: BP America
Location/API #: 067-06962
Date: 5-3-2019



Photo 1. View of the northern project area from the northeastern corner facing westward.



Photo 2. View of Canada thistles (*Cirsium arvense*) within the interim reclamation area. Approximately 1000 individuals observed.



Photo 3. View of area within the southern project area where sediment flows off of the southern edge of the working area into the southern interim reclamation area.



Photo 4. View of a project reference area north of the project area.