

Inspected FacilitiesFacility ID: 450197 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

On 5/6/2019, I Adam Kraich, performed a sound audit of the McGirr 26-L location, owned and operated by Extraction Oil & Gas.

I performed the audit at 40.36891, -104.96793.
Noise sources appear to be power generation equipment, located on northwest corner of production facility.

The audit began at approximately 12:34, and concluded at 12:55.

Audit revealed an LEQ 1 average of 60.7 DB, indicating noncompliance with rule 802.b

See attachments for sound audit detail, weather data, and inspection photos.

Corrective Action: Comply with rule 802.bDate: 05/09/2019**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402034843	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816721
694400151	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816717
694400152	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816718