


**Inspection Photos**  
**Location Name: Bower 10-24**  
**Location ID: 302718**



**Photo 1: Wellhead**



**Photo 2: Centralized Tank Battery**



**Inspection Photos**  
**Location Name: Bower 10-24**  
**Location ID: 302718**



**Photo 3: No NFPA placard on produced water tank.**



**Photo 4: Stained soil inside east separator house.**

