

Inspection Photos
Location Name: Linnebur #24-1
Location ID: 320225



Pic 1 separator unused equipment/trash



Pic 2 trash in separator house

Inspection Photos
Location Name: Linnebur #24-1
Location ID: 320225



Pic 3 pit & fence in disrepair



Pic 4 pit

Inspection Photos
Location Name: Linnebur #24-1
Location ID: 320225



Pic 5 gas meter run removed



Pic 6 no wellhead sign

Inspection Photos
Location Name: Linnebur #24-1
Location ID: 320225



Pic 7 unused equipment



Pic 8 trash on location

Inspection Photos
Location Name: Linnebur #24-1
Location ID: 320225



Pic 9 tank & Berm



Pic 10 location.