

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 1 possible spill



Pic 2 possible spill

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 3

Pic 4

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 5 unused equipment.



Pic 6 unused equipment

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 7 stained soil

Pic 8

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 9



Pic 10 possible leak on tank

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 11



Pic 12 pit no netting

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 13 pit



Pic 14 pit

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 15



Pic 16

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 17



Pic 18 no netting on water tank.

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



Pic 19 trash



Pic 20 possible leak on separator

Inspection Photos
Location Name: Schug Harland K #1
Location ID: 319991



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.95868, -103.75309, 4563.4ft, 234°
05/13/2019 12:22:28

Pic 21 possible leak in separator house



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.95866, -103.75297, 4567.8ft, 326°
05/13/2019 12:44:45

Pic 22 unused pump jack on location.