

Final Reclamation Inspection

May 13, 2019

Operator: BATES* JAMES EDWARD - 6575

API #: 05-001-06796

Inspection Document #: 697500096

Adams County, CO

SESE Section 7 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 1. Photo taken from a tank battery, facing Northwest. Operator has not performed all Final Reclamation activities at the Location (i.e., seeding).

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 2. Photo taken from the tank battery location, facing East. Equipment (i.e., risers) remains at location. This was a shared tank battery location and appears to be equipment from the other Operator. COGCC staff is reviewing this information and will coordinate with the Operator.

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 3. Photo taken from the tank battery location, facing Northeast. Debris left on location. This appears to be from another Operator. Operator might have to coordinate with the Operator to get this removed from location.