

Interim Reclamation and Stormwater Inspection

May 13, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 434399

Inspection Document #: 697500100

Adams County, CO

NENE Section 18 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Photo 1. Photo taken from the entrance of location, facing Southeast. Photo illustrates that interim reclamation has not been performed. This location is not in compliance with Rule 1003 standards.



Photo 2. Photo taken from the entrance of location, facing Southwest. Photo illustrates production equipment associated with the location.

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Photo 3. Photo taken from southern location, facing East. Photo illustrates the topsoil stockpile which appears to be in compliance with Rule 1002.c.



Photo 4. Photo taken from the southern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Photo 5. Photo taken from the southwestern location, facing West. Photo illustrates stormwater erosion. Operator has failed to properly stabilize cut slopes to minimize erosion and site degradation.

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Photo 6. Photo taken from a portion of the location. Photo illustrates a List B Colorado noxious weed, Musk thistle.

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Photo 7. Photo taken from location, facing East. Photo illustrates unused equipment.

Inspection Photos
Location Name: Willow Bend LD Pad
Location ID: 434399



Aerial photo taken from 2017. This is the current state as of 5/13/2019 which is not in compliance with Rule 1003.