

Inspection Photos

Loc#447512

Operator: Sandridge

Inspection Number: 692400970

Inspection Date: 5/8/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast. Note Debris in foreground.

May 8, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512



Photo#2:
Peters 0781 9-13H12 API# 057-06584. Pallet covering what Operator identified as mouse hole.



Photo#3:
Close up of mouse hole showing overflow of oily waste.

May 8, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: Sandridge Open Range Loc#447512



Photo#4:

Peters 0781 10-12H13 (Well sign did not correlate with API#s). Pallet covering what Operator identified as mouse hole.

May 8, 2019



Photo#5:

Close up of mouse hole showing overflow of oily waste.



Photo#6:
View to East to pad from lower level where supplies are stored.

May 8, 2019




Photo#7:
Supplies are being stored off of the compacted pad area. Retention pond in background. View to NW.



Photo#8:
Lower auxiliary road and BMPs do not appear to have been maintained

May 8, 2019



Photo#9:
View of area where supplies are being stored off of the compacted pad.



Photo#10:
Various piles of unidentified soil & soil mixed with gravel were noted stockpiled in different areas of Location.

May 8, 2019

Photo#11:
Various piles of unidentified soil & soil mixed with gravel were noted stockpiled in different areas of Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512



Photo#12:
Various piles of unidentified soil & soil mixed with gravel were noted stockpiled in different areas of Location.

May 8, 2019



Photo#13:
Various piles of unidentified soil & soil mixed with gravel were noted stockpiled in different areas of Location.



Photo#14:
Various debris & trash remains on site.

May 8, 2019



Photo#15:
Various debris & trash remains on site.



Photo#16:
Drips, stained soil were noted on Location.

May 8, 2019



Photo#17:
Drips, stained soil were noted on Location.