

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2019

Submitted Date:

05/08/2019

Document Number:

694400153

FIELD INSPECTION FORM

Loc ID 440858 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440858	LOCATION	AC			-	Simpson FD Pad 15-219HN	AC

General Comment:

Inspected Facilities

Facility ID: 440858 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC
 Corrective Action: _____ Date: _____

Complaint

Comment: Inspection in response to complaint. 18#200447246
Field Inspector Assigned: Adam Kraich
Complaint Received:
Date: 5/2/2019
Complaint Contacted:
Date: 5/2/2019 @8:52
Location #: 440858
Inspection Document #: 694400153
Nature of complaint: Noise
Field Inspector Actions:
 On 5/2/2019, I received a complaint concerning low frequency (C-Scale) noise coming from the Simpson FD location, owned and operated by Great Western Oil & Gas Company.
 On 5/2/2019, I set a continuous sound monitor 25 from the residence as guided by rule 802.d. I began the sound audit 5/2/2019 @ approximately 9:52am. The audit was concluded on 5/6/2019 at approximately 8:47am. LEQ averages are isolated to nighttime hours only (7am to 7pm). Additionally, the hours from 4:30am to 7:00am are excluded from the study and LEQ averages due to wind speeds beyond those defined on rule 802.
 LEQ 2 average over the course of the audit is observed at 70.7DB. This indicates noncompliance under rule 802.d.
 See inspection document for corrective action detail.
 All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action: Comply with rule 802.d Date: 05/13/2019

COGCC Comments

Comment	User	Date
<u>Inspection in response to complaint.</u>	<u>kraicha</u>	<u>05/08/2019</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402036380	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818017
694400154	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818014

694400155	Waether Data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818015
694400156	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818016