

Final Reclamation Inspection

May 13, 2019

Operator: K P KAUFFMAN COMPANY INC- #46290

API: 05-001-07569

Inspection Document #: 697500102

Adams County, CO

SESW Section 8 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EDSTROM #3
API: 05-001-07569



Photo 1. Photo taken from a portion of the access road, facing North. Photo illustrates undesirable weedy annual vegetation, Cheatgrass and Kochia, throughout the access road.

Inspection Photos
Location Name: EDSTROM #3
API: 05-001-07569



Photo 2. Photo taken from a portion of the access road, facing South. Photo illustrates bare ground and undesirable weedy annual vegetation, Kochia and Cheatgrass.

Inspection Photos
Location Name: EDSTROM #3
API: 05-001-07569



Photo 3. Close up photo taken from a portion of the access road. Photo illustrates undesirable weedy annual vegetation, Kochia and Cheatgrass.

Inspection Photos
Location Name: EDSTROM #3
API: 05-001-07569



Photo 4. Photo taken from the well location, facing East. Photo illustrates bare ground and undesirable weedy annual vegetation, Kochia and Cheatgrass.

Inspection Photos
Location Name: EDSTROM #3
API: 05-001-07569



Photo 5. Reference photo taken east of the access road, facing North. Photo illustrates perennial vegetation which is not reflective throughout the disturbance area.