

Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 581063 | Date: 10/10/1984 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 581066 | Date: 3/2/1984 |
| Doc #: 317089 | Date: 4/2/1996 |
| Doc #: 500137172 | Date: 12/8/1997 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 4/2/1997, Passed PA inspection 12/8/1997.

Pit Status Review Summary:

Based on records review the pit was replaced by a cement water vault by inspection dated 4/2/1996. Well was plugged and passed final inspection 12/8/1997. Pit status has been changed to Closed.