

Inspection Photos

Loc#446527

Operator: Sandridge

Inspection Number: 692400966

Inspection Date: 5/8/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

May 8, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Pintail Loc#446527



Photo#2:
Erosion is occurring on SE corner of cut slope. Rutting behind equipment.

May 8, 2019



Photo#3:
Erosion is occurring on SE corner of cut slope, sediment is migrating onto Location.



Photo#4:

Areas, no longer needed for use have not been reclaimed.
Abandoned equipment.

May 8, 2019



Photo#5:

Stormwater concerns at NW corner of the site.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512