

Inspection Photos

API: 05-061-06365

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing south at the beginning of the access road. The cattle guard is filled in with sediment. There is also another cattle guard further down the road that is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 2. It appears water pools onto the access road. A new road has been made by vehicles avoiding this area when wet causing additional disturbance that needs to be reclaimed and prevented.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 3. It appears water pools onto the access road. A new road has been made by vehicles avoiding this area when wet causing additional disturbance that needs to be reclaimed and prevented.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 4. There is an unknown pipe riser along the access road that is rusted with possible leakage. Lat/Long: 38.44139, -103.06295



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 5. Well sign is posted at the pump jack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 6. There is oil stain soil around the pump jack. There is a 5 gallon bucket with no labels or secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 7. The berms are not sufficient the fencing around the equipment is not sufficient to prevent livestock entry. Unknown 5 gal container is stored near equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 8. There is various junk rusted equipment stored to the north of the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 9. There is a shed with various junk equipment inside. There is oil stained soil that can be seen in the photo. Extent is unknown.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 10. Facing toward the unused equipment. There are barrels with what appears to be oil with no labeling or containment. One barrel is tipped over with oil stained soil from spillage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 11. The barrels appear to full of oil with no cap and there is oil on the top surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 12. There is various junk debris scattered on the ground. Barrels with no labels or containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 13. There is a cement pad at the north side of the location which is unused equipment or debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019

Inspection Photos



Photo 14. There is barbed wire in piles which poses a risk to livestock in the area. There is a grey pile of what appears to be cement debris. This picture was taken at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06365 | Date: 5/15/2019