

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2019

Submitted Date:

05/16/2019

Document Number:

697300076

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob		jacob.evans@nblenergy.com	
Axelson, John		john.axelson@state.co.us	
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452531	SPILL OR RELEASE	CL	02/07/2018		-	GWAA 3-11, 12, 13, 1	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site condition at the time of inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Good.

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: NoComment: None observed.☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spill/Remediation:**

Comment: Annual Form 27 reports are required on remediation #11013. No updates have been filed since 02/07/2018. Passive SVE wells are still present on location and appear in good condition.

Corrective Action: Submit Form 27 update with COGCC including all laboratory analytical reports for all samples collected during the reporting period. COA on Document #401539112 states "Define the vertical extent of contamination in the vicinity of sample location SS-13".

Date: 06/30/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697300077	SVE wells	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825725
697300079	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825726