

# Inspection Photos

API: 05-061-06429

Operator: BERRY ENERGY INC

Inspection Date: 5/15/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-061-06429 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** Facing east at the location. Bare area remains with no crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06429 | Date: 5/15/2019

## Inspection Photos



**Photo 2.** Facing east at the location. Bare area remains with no crop growth. Approximately 350' x 100'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06429 | Date: 5/15/2019



## Inspection Photos



**Photo 3.** There is an unmarked pipe riser found approximately 700 ft. east of the location at Lat/Long: 38.41642, -103.00220.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06429 | Date: 5/15/2019