

Inspection Photos

API: 05-061-06376

Operator: BERRY ENERGY INC

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing toward the old access road. The recontouring was not performed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 2. Facing north along the access road. The two track road remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 4. There are two bare areas that remain approximately 12' x 12'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 5. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06376 | Date: 5/15/2019