

# Inspection Photos

API: 05-061-06456

Operator: BERRY ENERGY INC

Inspection Date: 5/15/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06456 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** Facing south toward the location. Vegetation has not fully established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06456 | Date: 5/15/2019

## Inspection Photos



**Photo 2.** Facing south toward the location. Vegetation has not fully established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06456 | Date: 5/15/2019

## Inspection Photos



**Photo 3.** Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06456 | Date: 5/15/2019