

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 1. Location looking north. (Central battery & injection well)

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 2. Location looking east. (Storage area)

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Condensate
Dripping out

Photo 3. Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 4. Condensate dripping out offload connection.



Photo 5. Gravel inside tank berm soaked with condensate.

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 6. Gravel inside tank berm soaked with condensate.



Photo 7. Condensate sheen on top of water inside tank berm.

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 8. Tank label without capacity, operator and phone number.



Photo 9. Buried tank without label.

Columbine Springs 8-11-4S-104W WDW

API: 05-103-08825

Inspection: 679704087



Photo 10. Container labels without contents.



Photo 11. Unlabeled containers stored without secondary containment.