



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

1120 Lincoln Street, Suite 801  
Denver, CO 80203

**Document #2100097**

May 20, 2019

Jeanette Myers, Deputy Water Commissioner Dist 17  
Department of Associations  
301 Colorado  
La Junta, CO 81050

Dear Jeanette,

In response to your recent complaint regarding open drilling pits on the Padilla #1 well pad located in Crowley county the Colorado Oil and Gas Conservation Commission (COGCC) conducted multiple field inspections of the location and requested that the operator close the drilling pits that were left open in violation of COGCC rules. On May 16, 2019 I conducted a field inspection (COGCC inspection #697000007) and found the drilling pits closed and backfilled. As a result of this inspection your complaint has been closed. COGCC inspection 697000007 is attached for your reference and will be posted publically on the COGCC website 7 days after issuance. The COGCC is continuing to work with the operator to resolve other issues on the location.

Sincerely,

Jason Kosola  
Environmental Protection Specialist - Southeast Colorado  
Colorado Oil and Gas Conservation Commission

Enclosures: COGCC Field Inspection #697000007

cc: John Axelson - COGCC East Environmental Supervisor  
Ryan Costa - COGCC Reclamation Specialist

P 303.894.2100 F 303.894.2109 [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

Commissioners: John H. Benton - Chair, Howard Boigon - Co-Vice Chair, Tommy Holton - Co-Vice Chair,  
Ashley L. Ager, James W. Hawkins, Kent Jolley, Erin A. Overturf, Dan Gibbs, Jill Hunsaker Ryan, MPH

Jared Polis, Governor | Dan Gibbs, Executive Director, DNR | Julie Murphy, Director | Jeff Robbins, Acting Director



**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2019

Submitted Date:

05/17/2019

Document Number:

697000007

**FIELD INSPECTION FORM**

Loc ID 436291 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10496  
Name of Operator: CRAZY 8 ENERGY LLC  
Address: 9122 COUNTY ROAD HH  
City: LAMAR State: CO Zip: 81052

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,	,	dnr_cogccenforcement@state.co.us	<a href="#">COGCC Enforcement</a>
Spitz, Joe	719-688-5466	joespitz1@hotmail.com	
Axelson, John		john.axelson@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
Mazotti, Joe		joemazotti@gmail.com	
Costa, Ryan		ryan.costa@state.co.us	
Riemenschneider, David	719-980-0590	dar1463@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436290	WELL	PA	04/26/2014	LO	025-06020	Padilla 1	EI

**General Comment:**

This is a follow up environmental inspection to document status of drilling pits. Pits were documents as still open on previous COGCC inspections [682600659](#) and [689900462](#). Photos attached to document site status at the time of inspection. No reclamation has been conducted at the time of this inspection.

No corrective actions from previous COGCC inspection have been performed. Pits have been closed but no pit closure documentation has been submitted to the COGCC as required on COGCC inspection [682600659](#) and [689900462](#). Operator should submit Form 27 with analytical results to area Environmental Protection Specialist immediately.

Corrective action dates from COGCC inspection [689900462](#) remain in effect. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c. The corrective actions need to be performed immediately.

**Inspected Facilities**

Facility ID: 436290 Type: WELL API Number: 025-06020 Status: PA Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000008	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4826615</a>

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



May 16, 2019 09:32:34  
38.15229N 103.89730W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



May 16, 2019 09:33:33  
38.15259N 103.89701W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



May 16, 2019 09:34:04  
38.15276N 103.89726W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



May 16, 2019 09:34:15  
38.15275N 103.89721W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019



Location Name: Padilla #1 API: 025-06020 Inspection Date: 5/16/2019

