

# Inspection Photos

API: 05-061-06271

Operator: SAMSON OIL COMPANY

Inspection Date: 5/15/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019



## Inspection Photos



**Photo 2.** The vegetation shown in previous photo is predominately weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019



## Inspection Photos



**Photo 3.** Facing north at the location. There are areas that are bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019

## Inspection Photos



**Photo 4.** Facing southeast at the location. There are areas that are bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019



## Inspection Photos



**Photo 5.** The soils seem somewhat compacted in areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019



## Inspection Photos



**Photo 6.** Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, among other native plants.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06271 | Date: 5/15/2019