

# Inspection Photos

API: 05-061-06366

Operator: SAMSON OIL COMPANY

Inspection Date: 5/15/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-061-06366 | Date: 5/15/2019

## Inspection Photos



**Photo 1.** Facing south along the access road. The vegetation shown below the yellow lined is weeds (Kockia). There is mostly weeds all along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06366 | Date: 5/15/2019



## Inspection Photos



**Photo 2.** Facing south toward the location. The green vegetation is predominately all weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06366 | Date: 5/15/2019



## Inspection Photos



**Photo 3.** Facing north toward the location. Desirable vegetation has not established at the location and there are predominately weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06366 | Date: 5/15/2019



## Inspection Photos



**Photo 4.** Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, among other native plants.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06366 | Date: 5/15/2019