

Construction and Stormwater Inspection

May 20, 2019

Operator: CUB CREEK ENERGY- #10542

Location ID: 456537

Inspection Document #: 697500141

Weld County, CO

NWNE Section 29 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: OLANDER PAD
Location ID: 456537



Photo 1. Photo taken from the entrance to location, facing East. Operator has failed to install a vehicle tracking device BMP. Operator is tracking out sediment and rutting up the entrance.

Inspection Photos
Location Name: OLANDER PAD
Location ID: 456537



Photo 2. Photo taken from the entrance to location, facing South. See comments under Photo 1.



Photo 3. Photo taken from the northern location, facing East. Operator has install initial stormwater BMPs prior to the start of construction per Rule 1002.f. Note: It appears silt fence stakes have been installed too far apart. Per Rule 1002.f., Operator shall install stormwater BMPs per good engineering practices.