

Pit Status Evaluation Form

Pit Overview:

Pit Name: BASELINE 13-2	Facility ID: 113860
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: OIL RESOURCES INC / 65175	
Updated Operator:	
Form 15 Pit Permit Doc #: 664625	Permit Date: 1977
Related Facilities: API # 05-001-07180 (Facility ID 201776), Location 376040	

County: Adams			
Township: 1S	Range: 68W	Section: 2	QQ: SWSW
Original Latitude/ Longitude: 39.988368 / -104.975955			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 664625 | Date: 1977 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 313747 | Date: 9/22/1989 |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 10/31/1977; passed final inspection 9/22/1989

Pit Status Review Summary:

Well was plugged and passed final reclamation inspection 7/28/1992. Pit status has been changed to Closed.