

County: Adams			
Township: 1S	Range: 67W	Section: 10	QQ:
Original Latitude/ Longitude: NA		/ NA	
Updated Latitude/ Longitude:		/	
Basis for Location Change:			

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---------------------------------------------|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698502 | Date: 4/4/1985 |
| | Doc #: 698499 | Date: 2/17/1989 |
| | Doc #: 500132925 | Date: 6/5/1995 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Wells PA'ed 5/1995; passed final inspection 6/5/1995

Pit Status Review Summary:

Based on records review the pit was replaced by a fiberglass tank by 1989 inspection. Wells were plugged and passed final reclamation inspection 6/5/1995. Pit status has been changed to Closed.