



WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

BEST IMAGE
AVAILABLE

Well Name KAHLER #1-A API Number 05 - 009 - 5012
Operator JACKSON Permit # NA
Location SUNE 9 35S 41W County BACA
Field GREENWOOD Inspector SHELTON

AL ☒ PA ☐ DA Inspection Results:

Well Status:

Pass(Y) Fail(☒ N) Date 10/2/92 ND DG WO PR SI TA

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES NO Returns
Rig BOP'S Stage Tool Depth Cmt. Vol.

Date of Inspection Before/During/After Completion

Prod. Csg. Set? Completion Rig/Activity
Drilling Pits: Closed Open Wellhead Installed: Sign: Yes No
Tank ID: Yes No N/A Skim Tank/Pit: Prod. Tanks: () BBLs
Equipment Meter Run: Yes No
Bradenhead Press: Fluid: No Yes Type Well Cat.

AL ☒ PA ☐ DA Inspection

Date Plugged: 7/92 Date Permit Expired:
Hole Plugged: Yes ☒ No Pits Backfilled: Yes ☒ No
Material Buried: Yes No N/A ☒ Site Clean: Yes No ☒
Bond Release OK: Yes No ☒ Fed Hole Marker: Yes No ☒

Date of Safety/Status Inspection 10/2/92

Comments: PA APPARENTLY OK / TBG + DEBRIS SCATTERED
AROUND SITE / SMALL CONC SEP PAS, SEP ON GROUND /
TUBULAR FENCING + WIRE FENCING REMAINS

Violations: Yes No Notice Sent: Yes No Date Sent:

Re: Kahle, 1-A

~~Months:~~ MB

Date:

This well did not pass
two months ago.

I am wondering if it
has been cleaned up, or
not.

Maybe a phone call to
Jackson is in order,
before making a trip to
the well.

Thanks,

JACKSON
PO Box 150

DES
12/10/92

BORGER TX 79008-0150