

**Inspection Photos**  
**Location Name: Baird A #2**  
**API: 05-067-09704**



**Carsonite pipeline markers along access road where release occurred.**



**Locked out/tagged out equipment as a result of Spill/Release Point ID #464472.**

**Inspection Photos**  
**Location Name: Baird A #2**  
**API: 05-067-09704**



**Stained soil along the side of the Baird A #4 pump jack.**



**Stained soil along the side of the Baird A #2 pump jack**



**Inspection Photos**  
**Location Name: Baird A #2**  
**API: 05-067-09704**



**Area impacted by Spill/Release Point ID #464472**



**Impacted irrigation ditch actively flood irrigating field adjacent to location.**