

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402051832
Date Received:
05/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sabre Beebe</u>	<u>970-779-9398</u>	<u>sabre.beebe@bpx.com</u>
<u>-</u>		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603392
Inspection Date: 11/29/2018 FIR Submit Date: 12/14/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 334002

Location Name: PATRICK, GARU GU-M34N7W Number: 29SWNW County: LA PLATA
Qtrqtr: SWN Sec: 29 Twp: 34N Range: 7W Meridian: M
Latitude: 37.162700 Longitude: -107.637740

FACILITY - API Number: 05-067-00 Facility ID: 301148

Facility Name: SPARKS B Number: 2
Qtrqtr: SWN Sec: 29 Twp: 34N Range: 7W Meridian: M
Latitude: 37.162700 Longitude: -107.637740

CORRECTIVE ACTIONS:

1 CA# 121096

Corrective Action: Stormwater controls need to be installed within the northern, northwestern, and southeastern project area to stabilize erosion. Northern wattles need replacement or repair.

Date: 03/01/2019

Response: CA COMPLETED Date of Completion: 05/03/2019

For erosion control and stabilization rock rundowns have been installed on location. Old wattles have been

Operator Comment: removed and the pad graded to direct stormwater flow into the rundowns. See attached photos

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: For erosion control and stabilization rock rundowns have been installed on location. Old wattles have been removed and the pad graded to direct stormwater flow into the rundowns. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/22/2019 6:06:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402051833	Compliance follow up form with photos
-----------	---------------------------------------

Total Attach: 1 Files