



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 9, 2019 7:55:06 AM MDT
Server Receive Date:	May 20, 2019 7:45:59 AM MDT
Reference Number:	20190520-18106879444
Location:	Unknown Location

Information

Name	colen@horizonenvservices.com
Date	May 8, 2019
Well Name	WIRT GAS UNIT D DK 2M
API Number	50670634000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

Mowed Russian thistle skeletons, sprayed musk thistle populations in the interim reclamation area.

Notes

Heavy musk thistle populations on east side of interim reclamation area.