

Form Information

| | |
|----------------------|---|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | May 9, 2019 10:52:36 AM MDT |
| Server Receive Date: | May 20, 2019 7:45:59 AM MDT |
| Reference Number: | 20190520-18106880169 |
| Location: | Unknown Location |

Information

| | |
|-----------------------|--|
| Name | colen@horizonenvservices.com |
| Date | May 8, 2019 |
| Location Name (Other) | Southern Ute 32-8 1-1 |
| Location API (Other) | 0506705202 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Seeding |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

Seeded and mulched P/A location, fixed small erosion channel, cut musk thistle plants on location.

Notes

Did not spray musk thistle cause of the seeding performed today. Thistle population was small.