

<b>County:</b> Adams			
<b>Township:</b> 1S	<b>Range:</b> 65W	<b>Section:</b> 3	<b>QQ:</b> SWSW
<b>Original Latitude/ Longitude:</b> NA		/ NA	
<b>Updated Latitude/ Longitude:</b>		/	
<b>Basis for Location Change:</b>			

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA              | Date: NA         |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 697973         | Date: 3/26/1985  |
|                                     | Doc #: 312129                               | Date: 9/8/1989   |
|                                     | Doc #: 894216                               | Date: 11/17/1999 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Well PA 10/27/1989, passed final inspection 11/9/1989, 11/17/1999.

#### Pit Status Review Summary:

Based on records review a 20x20 skim pit existed on location. Well was plugged and passed final reclamation inspections 11/9/1989 and 11/17/1999. Pit status has been changed to Closed.