

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402051782
Date Received:
05/21/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Sabre Beebe	970-779-9398	sabre.beebe@bpx.com
Inspections, All		SanJuanCOGCC@bp.com
Fischer, Alex		alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800391
Inspection Date: 12/10/2018 FIR Submit Date: 12/11/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326271

Location Name: RICHARDSON GAS UNIT G- Number: 1SWSE County: LA PLATA
N34N8W
Qtrqtr: SWSE Sec: 1 Twp: 34N Range: 8W Meridian: N
Latitude: 37.240140 Longitude: -107.693600

FACILITY - API Number: 05-067- -00 Facility ID: 216146

Facility Name: RICHARDSON G Number: 1
Qtrqtr: SWSE Sec: 1 Twp: 34N Range: 8W Meridian: N
Latitude: 37.240140 Longitude: -107.693600

CORRECTIVE ACTIONS:

1 ☒ CA# 120929

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 01/11/2019

Response: CA COMPLETED Date of Completion: 05/02/2019

Impacted soils excavated around the wellhead, placed in containment bag and transported to the IEI soil box at the BPX office to be remediated in batch remediation. See attached photos. Excavation holes back filled with

Operator
Comment: clean soils.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Impacted soils excavated around the wellhead, placed in containment bag and transported to the IEI soil box at the BPX office to be remediated in batch remediation. See attached photos. Excavation holes back filled with clean soils.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/21/2019 5:32:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402051782	FIR RESOLUTION SUBMITTED
402051784	Follow up form and photos

Total Attach: 2 Files