

## WELL SITE INSPECTION FORM



Well Name GLASSBURN #1 API Number 05 - 075 - 9222  
 Operator PATRICK DOHENY Permit # 90-849  
 Location NW1/4 23-10N-52W County LOGAN  
 Field BRULE Inspector R. VanSickle

## AL/PA/DA Inspection Results:

## Well Status:

Pass(Y) ☐ Fail(N) ☐ Date ☐ ND ☐ DG ☐ WO ☐ PR ☒ SI ☐ TA ☐

=====

Date of Inspection Before/During Drilling ☐

Surf. Csg. Size ☐ Setting Depth ☐ Cmt. Vol. ☐ WOC time ☐  
 Consistent with APD casing Program? YES ☐ NO ☐ Returns ☐  
 Rig ☐ BOP'S ☐ Stage Tool Depth ☐ Cmt. Vol. ☐

Date of Inspection Before/During/After Completion 11-16-90

Prod. Csg. Set? ☒ Completion Rig/Activity PUMPING  
 Drilling Pits: Closed ☒ Open ☐ Wellhead Installed: ☒ Sign: Yes ☒ No ☐  
 Tank ID: Yes ☒ No ☐ N/A ☐ Skim Tank/Pit: 1000 GAL Prod. Tanks: (2) 300 BBLs  
 Equipment FV-HT PU Meter Run: Yes ☐ No ☒  
 Bradenhead Press: ☐ Fluid: No ☐ Yes ☐ Type ☐ Well Cat. ☐

## AL/PA/DA Inspection

Date Plugged: ☐ Date Permit Expired: ☐  
 Hole Plugged: Yes ☐ No ☐ Pits Backfilled: Yes ☐ No ☐  
 Material Buried: Yes ☐ No ☐ N/A ☐ Site Clean: Yes ☐ No ☐  
 Bond Release OK: Yes ☐ No ☐ Fed ☐ Hole Marker: Yes ☐ No ☐

Date of Safety/Status Inspection ☐

Comments: 65' x 65' PIT, EST. 200+ BWPD.

Violations: Yes ☒ No ☐ Notice Sent: Yes ☐ No ☐ Date Sent: ☐