

Inspection Photos
Operator: BP America
Location/API #: 067-09661
Date: 5-17-2019



Photo 1. View of the southern project area from the southeastern corner facing westward.



Photo 2. View of wood debris and unused equipment within the working area of the well pad.



Photo 3. View of hoary cress (*Cardaria draba*) infestation within the southeastern project area.