

Pit Status Evaluation Form

Pit Overview:

Pit Name: UPRR BOX ELDER FARMS 12-13 **Facility ID:** 114449

Current Status: Unknown **Status Date:** 9/23/1999

Current Operator: NONE LISTED

Updated Operator: ROCKY MOUNTAIN PROD CO - 74890

Form 15 Pit Permit Doc #: NA **Permit Date:** NA

Related Facilities: API # 05-031-08483 (Facility ID 208866), Location 381496

County: Denver

Township: 2S **Range:** 65W **Section:** 13 **QQ:** SWNW

Original Latitude/ Longitude: NA / NA

Updated Latitude/ Longitude: /

Basis for Location Change:

Pit Inspection/Information Request:

Field Inspection Date: **Document #:**

Pit Still Present in Field: No

Visible Surface Impacts: ☐ Stressed Vegetation ☐ Surface Depression ☐ Stained Soil ☐ Other (see below)

Inspection Notes:

Operator Required to Submit Form: NA **Due Date:**

Form Request Sent To: **Sent Date:**

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664762 | Date: 3/20/1985 |
| | Doc #: 371311 | Date: 9/19/1990 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 12/15/1988, passed final inspection 9/19/1990

Pit Status Review Summary:

Well was plugged and passed final reclamation inspection 9/19/1990. Pit status has been changed to Closed.