

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



**Photo 1: Wellhead sign**



**Photo 2: (TA) Pumpjack**

Inspection Photos  
Location Name: Walton 25-D Production Facility  
Facility ID: 441527



**Photo 3: (TA) Pumpjack; NO WELL SIGN**



**Photo 4: (TA) Wellhead; NO SIGN**

Inspection Photos  
Location Name: Walton 25-D Production Facility  
Facility ID: 441527



**Photo 5: (TA) Wellhead; NO SIGN, UNUSED EQUIPMENT**



**Photo 6: (TA) Wellhead; NO SIGN, UNUSED EQUIPMENT**

Inspection Photos  
Location Name: Walton 25-D Production Facility  
Facility ID: 441527



**Photo 7: (TA) Wellhead; NO SIGN, UNUSED EQUIPMENT**



**Photo 8: (TA) Wellhead; NO SIGN, UNUSED EQUIPMENT**

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



**Photo 9: (TA) Wellhead; NO SIGN, UNUSED EQUIPMET**



**Photo 10: Unused Equipment North side of Location.**

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



**Photo 11: Unused Equipment in middle of two pumpjacks.**



**Photo 12: Unused Equipment South end of location next to south pumpjack.**

Inspection Photos  
Location Name: Walton 25-D Production Facility  
Facility ID: 441527



Photo 13: Centralized Tank Battery



Photo 14: No BBLs listed on Produced water tank.

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



**Photo 15: Stained soil – separator house**



**Photo 16: Stained soil – separator house.**

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



Colorado Oil and Gas Conservation Commission  
40.54793, -104.83287, 1500.9m, 168°  
May 22, 2019 14:24:10

**Photo 17: Stained soil – separator house**



Colorado Oil and Gas Conservation Commission  
40.54793, -104.83287, 1500.2m, 125°  
May 22, 2019 14:25:14

**Photo 18: Stained soil east side of compressor**

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



**Photo 19: Storm water - erosion**



**Photo 20: Unused risers; unused equipment**

**Inspection Photos**  
**Location Name: Walton 25-D Production Facility**  
**Facility ID: 441527**



Colorado Oil and Gas Conservation Commission  
40.54792, -104.83277, 1496.5m, 309°  
May 22, 2019 15:46:22

**Photo 21: Unused riser**