

Inspection Photos
Location Name: Federal #3-10-84
Location ID: 322496
Inspection Date: May 15, 2019



Photo #1 – Aerial view of the location. White square represents the pit (119465) location and red dot represents the well (05-045-06391) on location.



Photo #2 – Location sign.

Inspection Photos

Location Name: Federal #3-10-84

Location ID: 322496

Inspection Date: May 15, 2019



Photo #3 – NFPA placard on plastic drum (north of separator).



Photo #4 – NFPA placard on produced water tank (south of separator).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal #3-10-84
Location ID: 322496
Inspection Date: May 15, 2019



Photo #5 – Weeds near horizontal heated separator.



Photo #6 – View of pit looking south west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: : Federal #3-10-84

Location ID: 322496

Inspection Date: May 15, 2019



Photo #7 – View of separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources