



LEASE INSPECTION FORM

Date 6/6/85  
Operator D. W. JACKSON Field GREENWOOD  
Lease Name & No. #1 Emma Hamilton County DACA  
Tank Battery No. NONE Location NESW 3-35S-41W  
Legal Description

Type of Inspection General Pit

Water Inflow \_\_\_\_\_ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of Tank

SKIM TANK \_\_\_\_\_

Pit No. 1 100 BBL operator F/g TANK

Pit No. 2 10 x 25' open / dry / overgrown

Pit No. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

LEASE SIGN OK

TK & Pump POORLY <100% FENCED

RECOMMENDED ACTION (If Required) \_\_\_\_\_

INSPECTOR ROBERT L. VACLAVIK

BEST IMAGE  
AVAILABLE