

# Inspection Photos

5/23/2019

Operator: ALLISON DRILLING COMPANY INC -  
1350

Location ID: 402112

Inspection Doc. Number: 696200102  
Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: ALLISON DRILLING COMPANY INC - 1350  
Location ID: 402112



**Photo 1:** Photo taken from access road, west of the location, facing east. Photo show stained soils.



**Photo 2:** Photo taken from the well location, facing east. Photo shows stained and contaminated soils on the location.

**Inspection Photos**  
**Operator Name: ALLISON DRILLING COMPANY INC - 1350**  
**Location ID: 402112**



**Photo 3:** Photo taken from the south end of the location, facing north. Photo shows pipe riser remaining on location.



**Photo 4:** Photo taken from the southwest end of the pit, facing east. Photo shows pit has not been closer and stained/contaminated soils remain.



Inspection Photos  
Operator Name: ALLISON DRILLING COMPANY INC - 1350  
Location ID: 402112



**Photo 5:** Photo shows pipe debris remaining on pit



**Photo 6:** Photo taken from the southwest end of the pit, facing north. Photo shows pit has not been closer and stained/contaminated soils remain.

## Inspection Photos

Operator Name: ALLISON DRILLING COMPANY INC - 1350

Location ID: 402112



**Photo 7:** Photo shows stained/contaminated soils remaining at pit.



**Photo 8:** Photo shows pits have not been closed and stained/contaminated soils remaining at pit.



**Inspection Photos**  
**Operator Name: ALLISON DRILLING COMPANY INC - 1350**  
**Location ID: 402112**



**Photo 9:** Photo taken from the east of the pits, facing northeast. Photo shows unvegetated areas where stained/contaminated soils are also evident. Aerial imagery suggests possible historic spill or discharge from pits.



**Photo 10:** Photo taken from the east of the pits, facing north. Photo shows unvegetated areas where stained/contaminated soils are also evident. Aerial imagery suggests possible historic spill or discharge from pits.



Inspection Photos  
Operator Name: ALLISON DRILLING COMPANY INC - 1350  
Location ID: 402112



**Photo 11:** 2016 Google earth aerial imagery of the well, location and disturbed areas.

