

WELL SITE INSPECTION



00563438



WELL NAME Hal Pettigrew 2 API NUMBER 05 - 071 - 6119
OPERATOR JAMAICA NATL Oil PERMIT NUMBER 881248
LOCATION SESE 19-345-68W COUNTY Las Animas
FIELD w/c INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) ☐ DATE 8-25-89 WELL STATUS: FN ☐ FD ☐ WO ☐

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 12-17-89 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ☒ NO ☐ PITS BACKFILLED: YES ☒ NO ☐
MATERIAL BURIED: YES ☒ NO ☐ NA ☐ SITE CLEAN: YES ☒ NO ☐
BOND RELEASE OK: YES ☒ NO ☐ FED ☐ HOLE MARKER: YES ☐ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Resubmitted this form since computer did not
indicate previous inspection - Y.

Wooded, mountain area on ranch

BEST IMAGE
AVAILABLE