

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402056343

Date Received:

05/28/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Luke Reddy 970-515-1292 luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500098
Inspection Date: 05/13/2019 FIR Submit Date: 05/14/2019 FIR Status:

Inspected Operator Information:

Company Name: ANADARKO WATTENBERG OIL COMPLEX LLC Company Number: 10600
Address: 1099 18TH STREET #1800
City: DENVER State: CO Zip: 80202-1918

LOCATION - Location ID: 319793

Location Name: WIERMAN-61S67W Number: 7SESE County: ADAMS
Qtrqr: SESE Sec: 7 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.973760 Longitude: -104.924230

FACILITY - API Number: 05-001-00 Facility ID: 201393

Facility Name: WIERMAN Number: 1
Qtrqr: SESE Sec: 7 Twp: 1S Range: 67W Meridian: 6
Latitude: 39.973760 Longitude: -104.924230

CORRECTIVE ACTIONS:

1 CA# 125139

Corrective Action: Comply with Rule 1004.a to remove all debris. Date: 05/28/2019

Response: CA COMPLETED Date of Completion: 05/23/2019

Operator Comment: Risers and any remaining equipment on location are the responsibility of the operator. Kerr McGee Midstream removed all of it's equipment, which included the meter run, riser, and flowline from location in November 2018. It appears the remaining risers were the supply to the meter from the facility.

COGCC Decision: Not Approved

Operator response does not accurately address the corrective action to remove all debris from location.

COGCC
Representative: Corrective action remains open until resolved.

OPERATOR COMMENT AND SUBMITTAL

Comment: Risers and any remaining equipment on location are the responsibility of the operator. Kerr McGee Midstream removed all of it's equipment, which included the meter run, riser, and flowline from location in November 2018. It appears the remaining risers were the supply to the meter from the facility.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 05/28/2019 11:03:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402056343	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files