

# Inspection Photos

API: 05-071-07959

Operator: PRESCO INC

Inspection Date: 5/24/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 1.** There is erosion issues along the main road to the location.  
Lat/Long:37.00747,-104.47421. The road was widened during operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 2.** There is erosion issues along the main road to the location.  
Lat/Long:37.00708,-104.47368. The road was widened during operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 3.** Further along the road vegetation is well established and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 4.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 5.** The northwest bank has predominately undesirable weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 6.** A pit remains per approved variance request.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 7.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 8.** There are noxious weeds along the south bank (Canada thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019

## Inspection Photos



**Photo 9.** There is a pile of t-post and wire at the south side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07959 | Date: 5/24/2019