

Inspection Photos

Location Name: TANAKA BROS-61N69W 2NESE / TANAKA BROTHERS 1 Pit

Location ID 321259/ Pit Facility ID 114787



Photo 1 – Location Photo



Photo 2 – Location photo

Inspection Photos

Location Name: TANAKA BROS-61N69W 2NESE / TANAKA BROTHERS 1 Pit

Location ID 321259/ Pit Facility ID 114787



Photo 3 – Location photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TANAKA BROS-61N69W 2NESE / TANAKA BROTHERS 1 Pit

Location ID 321259/ Pit Facility ID 114787



Photo 4 – 1999 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TANAKA BROS-61N69W 2NESE / TANAKA BROTHERS 1 Pit

Location ID 321259/ Pit Facility ID 114787



Photo 5 – 2006 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TANAKA BROS-61N69W 2NESE / TANAKA BROTHERS 1 Pit

Location ID 321259/ Pit Facility ID 114787




Photo 6 – 2018 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources